

CCCM SITE MONITORING: Basare Camp


Township: Sittwe (Rakhine, MYANMAR)


May-2018


Geographic Data: Vil. Tract / Town : San Pya Ward


Village/Ward : Ah Nauk San Pya Ward


Demographic data


 **2,261**
people


 **397**
households



 **49%**
children



 **5%**
elderly

 **3**
new borns

 **2**
deaths


Total 49% 51%

Vulnerabilities data




Camp Management or Focal Point Agency: LWF

Community infrastructure damage



Shelter rehabilitation and repair



Sector Overview



CCCM	# of coordinations meetings with CMCs	1
	# of meetings with service providers	1
Community Based Group	# of meetings held	
Youth Development Group (YDG)	1	
Women Development Group (WDG)	1	
Peer to Peer Group	1	
Parent Teacher Association (PTA)	1	
Child Protection Group	1	
Child Development Group (CDG)	1	



Health	Health facility presence	Yes
	# of NGO clinics	2
	# of Government clinics	0
	IDPs access to nearby health facility	Yes

NFI

NFI	# of HHs receiving WaSH consumables (soap, towel)	397
------------	---	-----



Shelter	# of HHs receiving Sanitary Kits / Dignity Kits	0
	# of temporary shelters (8 – 10 units)	52
	# of informal / makeshift shelters	0
	Date of the last Shelter Cluster assessment	01-May-18



	Functional	Non-functional
# Lightings at Latrines	21	6
#Lighting at other areas of camps	0	0
WASH		
# of Hand Pumps	17	6 (26%)
# of Ponds	0	0
# of Latrines	105	15 (13%)
# of Solid Waste Management System	2	0



Service Delivery Actors in the Camp

